

Location	E	N
Fine Adjusted SR4	814938	810975
SR5	814326	810540
SR6	813553	810475
Fine Adjusted SR9	811325	809787
SR10	810561	809494
Fine Adjusted SR12	810359	808989
SR15	816037	810722
CE	810900	807690
CF	815720	807980

Title

Locations of Marine Water Quality Monitoring Station

OUTLYING ISLANDS SEWERAGE STAGE 2 SOUTH LANTAU SEWERAGE WORKS - INVESTIGATION

Figure no. Figure 5.1

THE GOVERNMENT OF THE HONG KONG SPECIAL ADMINISTRATIVE REGION DRAINAGE SERVICES DEPARTMENT

Prepared | Checked

BLACK & VEATCH HONG KONG LIMITED 博威工程顧問有限公司

Date | Scale

Figure 2.4 - Locations of Water Quality Monitoring Stations

File: T:\GIS\CONTRACT\0227541\Mxd\0227541_Marine_Water_Quality_Monitoring_Stations.mxd
Date: 5/8/2015